

#### DESCRIPTION OF CORNER EVIDENCE FOUND

THE EXISTING MONUMENT WAS DESTROYED DURING U.D.O.T. CONSTRUCTION PROJECT. POSITION OF CORNER REESTABLISHED USING DATA OBTAINED DURING PREVIOUS SURVEYS ON FILE IN THE COUNTY SURVEYOR'S OFFICE.

# DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THE CORNER

3 ALUMINUM PIPE & CAP MONUMENTS (2 1/2" DIAMETER) & 1 MAG SPIKE WITH BRASS WASHER, WERE SET IN ADJOINING SECTIONS. NO PHYSICAL MONUMENT HAS BEEN SET AT POSITION OF SECTION CORNER. REFERENCED AS SHOWN

#### BASIS OF BEARINGS

THE BASIS OF BEARINGS IS GEODETIC NORTH DERIVED FROM G.P.S. OBSERVATIONS AT A CONTROL POINT LOCATED AT LAT: 40°11'44.89818"N & LONG: 110°49'41.53922"W USING THE UTAH STATE G.P.S. VIRTUAL REFERENCE STATION CONTROL NETWORK MAINTAINED AND OPERATED BY THE AUTOMATED GEOGRAPHIC REFERENCE CENTER

### STATE PLANE COORDINATE DATA

(U.S. SURVEY FEET) NAD 83 UTAH CENTRAL ZONE

N: 7246773.961 E: 1824807.728 IATITUDF: 40°12'44.64830" N

**LONGITUDE:** 110°50'23.04611" W

PUBLIC LAND SURVEY SYSTEM GCDB ID NO. UT300030S0080W0\_100400

## CERTIFICATION

I <u>Jerry D. Allred</u>, Professional Land Surveyor, State of Utah, do hereby certify that I have performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve same

Date <u>22 SEP '16</u>

Jerry D. Allred, Professional Land Surveyor Certificate No. 148951 Duchesne County Surveyor

